

Safety Issue Type: Recalls

June 29 2023 NHTSA Campaign Number: 23V458000

Loose Fastener on Brake Booster Assembly

Brake master cylinder separation can cause a loss of brake function and increase the risk of a crash.

NHTSA Campaign Number 23V458000

Manufacturer Honda (American Honda Motor Co.)

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 124077

Summary

Honda (American Honda Motor Co.) is recalling certain 2020-2021 Civic, 2020-2023 Ridgeline, 2021-2023 Passport, 2021-2022 Pilot, and 2020 Acura MDX vehicles. The tie rod fastener that connects the brake booster and the brake master cylinder may have been improperly assembled during manufacturing, which can cause the brake master cylinder to separate from the booster assembly.

Remedy

Dealers will inspect and repair the brake booster assembly as necessary, free of charge. Owner notification letters are expected to be mailed August 7, 2023. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are VEU, AEV, and ZET.

Notes

Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.nhtsa.gov.

Affected Products (12)

Vehicle

MAKE	MODEL	YEAR
ACURA	MDX	2020
HONDA	CIVIC	2020-2021
HONDA	PASSPORT	2021-2023
HONDA	PILOT	2021-2022
HONDA	RIDGELINE	2020-2023

Associated Documents (2)

Defect Notice 573 Report

RCLRPT-23V458-1736.PDF 217.08KB

<https://static.nhtsa.gov/odi/rcl/2023/RCLRPT-23V458-1736.PDF>

Recall Acknowledgement

RCAK-23V458-8185.pdf 738.222KB

<https://static.nhtsa.gov/odi/rcl/2023/RCAK-23V458-8185.pdf>